
Approaching berth with inappropriate speed
Approaching berth at inappropriate angle
Failure to berth using rope or anchor
Pilot trained to berth in confined spaces
HM/P / C4-02.03
M
Manoeuvring
M.04b Berthing error
Rope or anchor failure
Boatmen trained to attach rope in time
Boatmen trained to attach rope to the right bollard
Foy / B5-02.03
Ensure the use of quality ropes
Anchor failure
VTS advise on location of anchor lines or other
VTS / B1-06.06
Surging failure
Competent crew